



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME MULBERRY PLACE			REINSPECTION DATE Not Specified	INSPECTOR Ngoc Le	DATE 9/14/2016
LOCATION ARROW ROUTE / VINEYARD, RANCHO CUCAMONGA, CA 91730			PERMIT EXPIRATION 8/31/2017	IDENTIFIER: Spa SERVICE: 008 - INSPECTION - ATTEMPTED	
TIME IN 4:02 AM	TIME OUT 11:53 AM	FACILITY ID FA0006099	RELATED ID PR0014904	PE 3623	RESULT: 00 - NOT APPLICABLE ACTION: 00 - NOT APPLICABLE


RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	37
volume (gal)	1,139
area (sq ft)	63
occupancy	62

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:
1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K996 Attempted Inspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: On 9/14/16, an inspection was attempted. Another inspection will be attempted at a later date.
	Not In Compliance	
	Violation Reference - HSC	

Description: An inspection was attempted today. Another inspection will be attempted at a later date.

Overall Inspection Comments

On 9/14/16, an inspection was attempted.

Another inspection will be attempted at a later date.

Signature(s) of Acknowledgement

SNA

NAME: SNA
TITLE:

Total # of Images: 0