



Public Health
Environmental Health Services



www.SBCounty.gov

NATURAL BATHING PLACES & SLIDES - OFFICIAL INSPECTION REPORT

FACILITY NAME 5TH AVENUE SWIM CLUB		DATE 6/29/2015	REINSPECTION DATE Next Routine	PERMIT EXPIRATION 6/30/2015
LOCATION 1235 FORD ST, REDLANDS, CA 92373			INSPECTOR James Gutman	
MAILING ADDRESS 615 BROOKSIDE UNIT A, REDLANDS CA 92373			IDENTIFIER: Swim Area	
			SERVICE: 001 - INSPECTION - ROUTINE	
TIME IN 1:26 PM	TIME OUT 2:20 PM	FACILITY ID FA0012803	RELATED ID PR0016782	PE 3806
			RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE	
			ACTION: 01 - NO FURTHER ACTION REQUIRED	

NATURAL BATHING PLACES & SLIDES - Artificial & Natural Bathing Place

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	0
volume (gal)	400,000
area (sq ft)	10,000
occupancy	500

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

38K588 AWRR - Water Quality - Non-Critical - Water pH 7.2 to 7.8

Compliance Date: Not Specified
Not In Compliance
Violation Reference - SBCC - 33.1126-33.1130

Inspector Comments: Measured water pH at 7.9. Maintain water pH between 7.2 and 7.8.

Violation Description: The pool operator shall maintain public pool water at pH 7.2 to 7.8.

38K626 AWRR - Enclosure - Non-Critical - Gates and doors self-closing and self-latching

Compliance Date: Not Specified
Not In Compliance
Violation Reference - SBCC - 33.1126-33.1130

Inspector Comments: Observed east gate not self-closing when opened inward toward pool area. Maintain gate locked until gate is repaired. Observed gate on west side self-closing and self-latching properly.

Violation Description: Gates and doors shall be equipped with self-closing and self-latching devices. Gates and doors shall be capable of being locked during times when the pool is closed. The self-latching device shall keep the gate or door securely closed. Gates and doors shall open outwardly away from the pool except where otherwise prohibited by law. The pool enclosure shall have at least one means of egress without a key for emergency purposes. The enclosure shall be constructed so that all persons will be required to pass through common pool enclosure gates or doors in order to gain access to the pool area. All gates and doors exiting the pool area shall open into a public area or a walkway accessible by all patrons of the pool.

38K666 AWRR - Maintenance - Public pool site maintenance

Compliance Date: Not Specified
Not In Compliance
Violation Reference - SBCC - 33.1126-33.1130

Inspector Comments: Observed drinking fountain not working. Repair drinking fountain as needed.

Violation Description: The pool operator shall keep all parts of the public pool site well-maintained, including, but not limited to, the public pools, water treatment systems, ancillary facilities, signs, showers, toilets, dressing facilities, drinking fountains, diaper-changing stations, floors, walls, partitions, doors, and lockers.

Overall Inspection Comments

Conducted routine inspection of pool.

Note: Observed bottles of bleach stored in mens restroom. Recommend storing chemicals in area not accessible to swimmers. Corrected on site.

Continue diligent efforts to maintain free chlorine level at or above 1.0 ppm.

Signature(s) of Acknowledgement



Public Health
Environmental Health Services

NATURAL BATHING PLACES & SLIDES - OFFICIAL INSPECTION REPOR

FACILITY NAME 5TH AVENUE SWIM CLUB	DATE 6/29/2015
LOCATION 1235 FORD ST, REDLANDS, CA 92373	INSPECTOR James Gutman

NAME: Diane Shimota
TITLE: Board member/life guard

Total # of Images: 0