





RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME AMADOR ON ROUTE 66			DATE 9/4/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 8/31/2016
LOCATION 8090 CORNWALL , RANCHO CUCAMONGA, CA 91739			INSPECTOR Nick Thalasinis		
MAILING ADDRESS 1855 SAMPSON AV, CORONA CA 92879-6009			IDENTIFIER: Pool		
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION		
TIME IN 9:50 AM	TIME OUT 10:10 AM	FACILITY ID FA0015706	RELATED ID PR0020871	PE 3620	RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED
			ACTION: 01 - NO FURTHER ACTION REQUIRED		

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: _____
	Not In Compliance	
	Violation Reference - HSC	

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

Observed the trees were cut back as directed by Supervisor Paula Harold.

Signature(s) of Acknowledgement

NAME:
TITLE:
Total # of Images: 0