



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME PROMONTORY		REINSPECTION DATE Not Specified		INSPECTOR Yanan Zhu	DATE 9/2/2016
LOCATION 13156 PINNACLE CT, CHINO HILLS, CA 91709				PERMIT EXPIRATION 8/31/2015	IDENTIFIER: Spa
TIME IN 2:35 PM	TIME OUT 3:12 PM	FACILITY ID FA0007322	RELATED ID PR0014642	PE 3623	SERVICE: 037 - POOL/SPA - BILLABLE INSPECTION SERVIC RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN




RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	47
volume (gal)	1,408
area (sq ft)	79
occupancy	8

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified	Inspector Comments: a Re-reinspection was conducted today to determine the compliance from prior reinspection. Observed spa water disinfectant residual level was at 4.1 PPM free-chlorine. The disinfectant residual level is in compliance at the time of this re-reinspection. Observed underwater spa light was functioning properly, GFCI unit was tested and functioning properly, and no water observed inside the underwater spa light at the time of this re-reinspection. The underwater spa light is in compliance at the time of this re-reinspection. The health permit to operate is hereby reinstated and facility may open.
	Not In Compliance	
	Violation Reference - HSC	

Description: The health permit to operate is hereby reinstated and facility may open.

36K993 Re-Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: a Re-reinspection was conducted today to determine the compliance from prior reinspection. Observed spa water disinfectant residual level was at 4.1 PPM free-chlorine. The disinfectant residual level is in compliance at the time of this re-reinspection. Observed underwater spa light was functioning properly, GFCI unit was tested and functioning properly, and no water observed inside the underwater spa light at the time of this re-reinspection.
	Not In Compliance	
	Violation Reference - HSC	

Description: Billable re-reinspection conducted at the time to determine compliance from prior inspection.

36K508 Water Quality – Non-Critical – Water pH 7.2 to 7.8

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Observed spa water pH at 7.0 at the time of re-reinspection. Maintain spa water pH at 7.2 to 7.8.
	Not In Compliance	
	Violation Reference - HSC - 65530	

Violation Description: The pool operator shall maintain public pool water at pH 7.2 to 7.8.

Overall Inspection Comments

No summary comments have been made for this inspection.



Public Health
Environmental Health Services

www.SBCounty.gov
www.SBCounty.gov/dph/dehs

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME PROMONTORY	DATE 9/2/2016
LOCATION 13156 PINNACLE CT, CHINO HILLS, CA 91709	INSPECTOR Yanan Zhu

Signature(s) of Acknowledgement

NAME:

TITLE:

Total # of Images: 0