



Public Health

Environmental Health Services

RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REP

FACILITY NAME ALTA LOMA HIGH SCHOOL		DATE 7/23/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION
LOCATION 8880 BASELINE RD, RANCHO CUCAMONGA, CA 91701			INSPECTOR Bennetta Betbadal	
MAILING ADDRESS 276 N SECOND AVE UPLAND, CA 91786			IDENTIFIER: None	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT			SERVICE: 126 - PLAN CHECK FIELD INSPECTION	
TIME IN 8:50 AM	TIME OUT 10:10 AM	FACILITY ID FA0006436	RELATED ID SR0065247	PE 3712
			RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU	
			ACTION: 03 - REINSPECTION REQUIRED	

RECREATIONAL HEALTH PLAN CHECK - PInCk Pool New 1,000-Up SqFt

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

37K010 Ancillary - Drinking Fountain

Compliance Date: Not Specified

Inspector Comments: Provide a drinking fountain within the pool vicinity.

Not In Compliance

Reference - CCR 24 - 3116B

Description: Provide a drinking fountain within the pool vicinity.

37K064 Enclosure - General - 4"

Compliance Date: Not Specified

Inspector Comments:

Not In Compliance

Reference - CCR 24 - 3118B(a)

Description: Openings, holes or gaps in the enclosure, doors and/or gates shall not allow the passage of a four (4) inch diameter sphere.

37K510 Plans - Preliminary Inspection

Compliance Date: Not Specified

Inspector Comments: Pre-plaster inspection.

Not In Compliance

Reference - Reference Number - SBC Policy

Continue as per approved plans.

Authorized to plaster.

Before filling the pool ensure that fence and gates are in place.

Description: Preliminary inspection

Overall Inspection Comments

Per Authorized plans , per plan check supervisor's approval urinal is not required at restrooms by the pool since locker rooms and restrooms are near the pool area are equipped with urinals.

Signature(s) of Acknowledgement

NAME:

TITLE:

Total # of Images: 0