






Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME HAMPTON INN & SUITES			DATE 7/15/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 4/30/2016
LOCATION 250 N 9TH ST, COLTON, CA 92324				INSPECTOR John Babalola	
MAILING ADDRESS 105 DECKER CT STE 500, IRVING TX 75062			<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT IDENTIFIER: Pool SERVICE: 153 - RESPONSE TO POOL SURVEY RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN		
TIME IN 1:25 PM	TIME OUT 1:52 PM	FACILITY ID FA0008659	RELATED ID PR0014087	PE 3620	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	60
required flow (gpm)	40
volume (gal)	No Data
area (sq ft)	No Data
occupancy	20

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified	Inspector Comments: The pool water is now clear and clean. The bottom of the pool is now visible. Therefore, the permit that was suspended on 7-7-15 is now re-instated. The pool can now re-open for use. Other violations noted on the inspection report of 7-2-15 have been corrected.
	Not In Compliance	
	Violation Reference - HSC	

Description: The health permit to operate is hereby reinstated and facility may open.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: ruben castro
 TITLE: chief engineer

Total # of Images: 0