



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME EUREKA MANOR				REINSPECTION DATE Not Specified	INSPECTOR Anies Kondoker	DATE 10/28/2015
LOCATION 1525 E EUREKA ST, SAN BERNARDINO, CA 92404				PERMIT EXPIRATION	IDENTIFIER: None	
TIME IN 11:16 AM	TIME OUT 11:39 AM	FACILITY ID FA0008381	RELATED ID CO0052293	PE 3620	SERVICE: 037 - POOL/SPA - BILLABLE INSPECTION SERVIC RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED	


RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K993 Re-Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: _____
	Not In Compliance	
	Violation Reference - HSC	

Description: Billable re-reinspection conducted at the time to determine compliance from prior inspection.

36K999 Complaint Inspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: _____
	Not In Compliance	
	Violation Reference - HSC	

Description: A complaint report has been received by Environmental Health.

36K572 Maintenance – Pool shell cleanliness; slime and algae

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Observed debris accumulation on pool surface and bottom. Ensure to maintain clean.
	Not In Compliance	
	Violation Reference - HSC - 65533	

Violation Description: (a) The pool operator shall maintain clean pool water while the public pool is in use. The pool operator shall not allow debris, including, but not limited to, floating scum, sputum, trash, or leaves, to accumulate in the public pool. The pool operator shall ensure that water levels are maintained and operated to remove such material continuously through the pool skimming system in accordance with section 3136B, Title 24, California Code of Regulations.

(b) The pool operator shall clean the bottom, sides, and other surfaces of the public pool as often as necessary to keep the bottom, sides, and public pool surfaces clean and free of slime and algae.

Overall Inspection Comments



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

<small>FACILITY NAME</small> EUREKA MANOR	<small>DATE</small> 10/28/2015
<small>LOCATION</small> 1525 E EUREKA ST, SAN BERNARDINO, CA 92404	<small>INSPECTOR</small> Anies Kondoker

Observed main drains of both pool and spa clearly visible from outside the fence.

Unable to gain access to the pool enclosure and pump room.

Office is closed at this time.

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0