



**Public Health**  
Environmental Health Services



www.SBCounty.gov

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME MONTEREY VILLAS APTS		DATE 6/12/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 5/31/2016
LOCATION 7000 LA PRAIX , HIGHLAND, CA 92346			INSPECTOR Anies Kondoker	
MAILING ADDRESS 1 ORCHARD 230, LAKE FOREST CA 92630-8300			IDENTIFIER: Pool	
TIME IN 5:03 PM			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME OUT 5:14 PM			RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE	
FACILITY ID FA0005742			ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	
RELATED ID PR0013510			PE 3620	

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	50
volume (gal)	17,854
area (sq ft)	616
occupancy	20

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K992 Permit Reinstatement**

POINTS <b>NA</b>	Compliance Date: Not Specified	Inspector Comments:
	Not In Compliance	
	Violation Reference - HSC	

**Description:** The health permit to operate is hereby reinstated and facility may open.

**36K994 Reinspection**

POINTS <b>NA</b>	Compliance Date: Not Specified	Inspector Comments:
	Not In Compliance	
	Violation Reference - HSC	

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

The gate is self-closing and self-latching.

**Signature(s) of Acknowledgement**

NAME:  
TITLE:  
Total # of Images: 0