



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>SHADY TRAILS PARKHOUSE</b>		REINSPECTION DATE <b>Not Specified</b>		INSPECTOR <b>Lizeth Lopez</b>	DATE <b>9/16/2016</b>
LOCATION <b>15800 S PARK LN, FONTANA, CA 92336</b>		PERMIT EXPIRATION <b>3/31/2017</b>		IDENTIFIER: Wading Pool SERVICE: 001 - INSPECTION - ROUTINE	
TIME IN <b>2:04 PM</b>	TIME OUT <b>2:34 PM</b>	FACILITY ID <b>FA0014449</b>	RELATED ID <b>PR0019093</b>	PE <b>3621</b>	RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED

**RECREATIONAL HEALTH - Public Pool - Additional Pool at Facility**



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

**97**  
SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	38
volume (gal)	2,246
area (sq ft)	256
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K508 Water Quality – Non-Critical – Water pH 7.2 to 7.8**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	Inspector Comments: Observed pH to be measured at 7.9.
	Not In Compliance	
	Violation Reference - HSC - 65530	Maintain pH between the required range of 7.2 and 7.8.

**Violation Description:** The pool operator shall maintain public pool water at pH 7.2 to 7.8.

**36K518 Water Quality – Cyanuric acid concentration**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	Inspector Comments: Observed cyanuric acid concentration to be measured "[above] range".
	Not In Compliance	
	Violation Reference - HSC - 65530	Maintain cyanuric acid concentration below the maximum of 100.0 ppm.

**Violation Description:** The maximum concentration of cyanuric acid in public pool water shall not exceed 100.0 ppm.

**36K552 Equipment - Flow meter provided**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	Inspector Comments: Observed non-functional flow meter.
	Not In Compliance	
	Violation Reference - CCR 24 - 3125B.3	Repair or replace flow meter. Ensure flow rate meets the turnover time requirements.

**Violation Description:** A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow and installed according to the manufacturer's written instructions with increments in the range of normal flow.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**



**Public Health**  
Environmental Health Services

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME SHADY TRAILS PARKHOUSE	DATE 9/16/2016
LOCATION 15800 S PARK LN, FONTANA, CA 92336	INSPECTOR Lizeth Lopez



NAME: Mario Lopez  
TITLE: Facility Coordinator

Total # of Images: 0