



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME COGUA AQUATICS				REINSPECTION DATE Not Specified	INSPECTOR Casey Salazar	DATE 11/24/2015
LOCATION 14523 RAMONA AV, CHINO, CA 91710				PERMIT EXPIRATION	IDENTIFIER: None	
TIME IN 9:27 AM	TIME OUT 9:51 AM	FACILITY ID FA0028829	RELATED ID CO0052908	PE 3620	SERVICE: 004 - COMPLAINT - INITIAL RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K999 Complaint Inspection

POINTS
NA

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC

Inspector Comments: Complaint states there is black mold growing behind washer and dryers in rear of facility.

Observed no mold behind washing machine. Observed black staining on right side of wall; however, it does not appear to be mold. Per owner, every month a company is hired to deep clean pool enclosure and facility has a maintenance person that does daily cleaning.

Note: Observed several drain flies in shower area. Ensure flies are eliminated from pool enclosure.

Description: A complaint report has been received by Environmental Health.

Overall Inspection Comments

Complaint inspection conducted

Signature(s) of Acknowledgement

TAIE C.

NAME:
TITLE:

Total # of Images: 0