




RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME RED ROOF INN			DATE 9/9/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2016
LOCATION 13409 MARIPOSA RD, VICTORVILLE, CA 92392				INSPECTOR Melissa Nano	
MAILING ADDRESS 106 CITRUS RANCH RD, SAN DIMAS CA 91773			<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT IDENTIFIER: North Spa SERVICE: 008 - INSPECTION - ATTEMPTED RESULT: 00 - NOT APPLICABLE ACTION: 00 - NOT APPLICABLE		
TIME IN 10:51 AM	TIME OUT 11:17 AM	FACILITY ID FA0004486	RELATED ID PR0013927	PE 3623	

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	27
volume (gal)	809
area (sq ft)	50
occupancy	5

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K996 Attempted Inspection

POINTS
NA

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - HSC

Inspector Comments:

An attempted inspection was conducted today on 9/9/15.

Observed spa already voluntarily closed to the public due to pump repair. Pump was observed off and not operating. Operator may possibly drain pool depending on what is needed for repair. Operator states spa shall be ready in a week.

Contact Environmental Health Services when pool is ready to reopen.

Description: An inspection was attempted today. Another inspection will be attempted at a later date.

Overall Inspection Comments

If there are any questions, please contact Environmental Health Services or Melissa Nano at (800) 442-2283.

Signature(s) of Acknowledgement

NAME: refer to pool OIR (Mike)
 TITLE:

Total # of Images: 0