



**Public Health**  
Environmental Health Services




www.SBCounty.gov

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

|  |                             |                                 |   |                                       |
|--|-----------------------------|---------------------------------|---|---------------------------------------|
| FACILITY NAME<br><b>OSBUN SQUARE HOA</b>   |                             | DATE<br><b>5/13/2015</b>        | REINSPECTION DATE<br><b>Not Specified</b> | PERMIT EXPIRATION<br><b>7/31/2015</b> |
| LOCATION<br><b>2350 N OSBUN RD 50, SAN BERNARDINO, CA 92404</b>  |                             |                                 | INSPECTOR<br><b>Anies Kondoker</b>        |                                       |
| MAILING ADDRESS<br><b>273 W RIALTO AV, RIALTO CA 92376</b>   |                             |                                 | IDENTIFIER: Pool                          |                                       |
| <input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT |                             |                                 | SERVICE: 008 - INSPECTION - ATTEMPTED     |                                       |
| TIME IN<br><b>10:31 AM</b>   | TIME OUT<br><b>10:44 AM</b> | FACILITY ID<br><b>FA0003187</b> | RELATED ID<br><b>PR0015467</b>            | PE<br><b>3620</b>                     |
| RESULT: 00 - NOT APPLICABLE  |                             |                                 |   |                                       |
| ACTION: 00 - NOT APPLICABLE  |                             |                                 |   |                                       |

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

|                   |
|-------------------|
| Ideal             |
| In Compliance     |
| Not in Compliance |



|                     |         |
|---------------------|---------|
| temperature (°F)    | No Data |
| observed flow (gpm) | No Data |
| required flow (gpm) | No Data |
| volume (gal)        | No Data |
| area (sq ft)        | No Data |
| occupancy           | No Data |

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K996 Attempted Inspection**

|                            |                                |                                     |
|----------------------------|--------------------------------|-------------------------------------|
| <b>POINTS</b><br><b>NA</b> | Compliance Date: Not Specified | <b>Inspector Comments:</b><br>_____ |
|                            | Not In Compliance              |                                     |
|                            | Violation Reference - HSC      |                                     |

**Description:** An inspection was attempted today. Another inspection will be attempted at a later date.

**Overall Inspection Comments**

Unable to gain access to the pool enclosure.

**Signature(s) of Acknowledgement**

NAME:  
TITLE:  
Total # of Images: 0