



Public Health
Environmental Health Services



www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME ZEINA VILLAGE CONDOS			DATE 7/6/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 3/31/2015
LOCATION 1200 E HIGHLAND AV, REDLANDS, CA 92374			INSPECTOR Veronica Vazquez		
MAILING ADDRESS 8599 HAVEN STE 201, RANCHO CUCAMONGA CA 91730			IDENTIFIER: Spa		
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION		
TIME IN 3:23 PM	TIME OUT 3:24 PM	FACILITY ID FA0015253	RELATED ID PR0020210	PE 3623	RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE
			ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN		

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	37
volume (gal)	1,118
area (sq ft)	78
occupancy	7

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Spa is hereby open. Removed closure sign.
	Not In Compliance	
	Violation Reference - HSC	

Description: The health permit to operate is hereby reinstated and facility may open.

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Observed free chlorine at 5 ppm in spa water. Spa is hereby open. Removed closure sign.
	Not In Compliance	
	Violation Reference - HSC	

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

Verify spa light is in good repair. Provide access to equipment room.
 Call Veronica Vazquez at (800) 442-2283 with questions.

Signature(s) of Acknowledgement

NAME:
 TITLE:
 Total # of Images: 0