



**Public Health**  
**Environmental Health Services**




www.SBCounty.gov

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME AMADOR ON ROUTE 66			DATE 8/18/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 8/31/2015
LOCATION 8090 CORNWALL, RANCHO CUCAMONGA, CA 91739				INSPECTOR Nick Thalasinis	
MAILING ADDRESS 1760 CALIFORNIA AV STE 101, CORONA CA 92881				IDENTIFIER: Pool	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT				SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME IN 9:05 AM	TIME OUT 9:25 AM	FACILITY ID FA0015706	RELATED ID PR0020871	PE 3620	RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K994 Reinspection**

**POINTS**  
**NA**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - HSC

**Inspector Comments:** Reinspection of the trees within the five (5) foot perimeter of the pool fence.

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

Inspector (Nick Thalasinis) and his Supervisor (Paula Harold) met with HOA representatives to discuss the fencing/enclosure violation issued on 7/10/2015 for the removal of trees located next to the pool enclosure. During site visit, eight Magnolia trees were observed to be located less than 5 feet from the outside of the pool fence. The representatives stated the trees had been there for seven years. Some of the trees can be considered a climbable structure. This situation was discussed and it was agreed upon by all parties to trim back the trees so branches are not hanging over or located right next to the pool enclosure. Facility has one (1) week to comply.

**Signature(s) of Acknowledgement**

NAME:  
 TITLE:

Total # of Images: 0