



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>EUREKA MANOR</b>			REINSPECTION DATE <b>Not Specified</b>	INSPECTOR <b>Anies Kondoker</b>	DATE <b>10/21/2015</b>
LOCATION <b>1525 E EUREKA ST, SAN BERNARDINO, CA 92404</b>			PERMIT EXPIRATION	IDENTIFIER: None	
TIME IN <b>11:59 AM</b>	TIME OUT <b>12:28 PM</b>	FACILITY ID <b>FA0008381</b>	RELATED ID <b>CO0052293</b>	PE <b>3620</b>	SERVICE: 037 - POOL/SPA - BILLABLE INSPECTION SERVIC RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU ACTION: 03 - REINSPECTION REQUIRED


**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:  
1. Meet the latest ANSI/APSP-16 performance standard  
2. Be rated for the maximum designed flow-rate of the pump  
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K993 Re-Reinspection**

**POINTS**  
**NA**

Compliance Date: Not Specified  
Not In Compliance  
Violation Reference - HSC

**Inspector Comments:**

**Description:** Billable re-reinspection conducted at the time to determine compliance from prior inspection.

**36K514 Water Quality – Critical – Water clarity**



**POINTS**  
**5**

Compliance Date: Not Specified  
Not In Compliance  
Violation Reference - HSC - 65527

**Inspector Comments:** Observed pool water to be cloudy with some debris accumulation on pool surface. Bottom of the pool is not visible from outside the fence.

**Violation Description:** The pool operator shall maintain clear pool water while the public pool is in use. The pool operator shall close the public pool if the bottom of the pool at the maximum depth is not clearly visible from the deck. The pool operator shall not reopen the public pool for use until the pool water is clean and clear, and the bottom of the pool at the maximum depth is clearly visible from the deck. If the bottom of the pool is not visible 48 hours following inspection and closure by the enforcing agent, the enforcing agent may order the pool drained.

**Overall Inspection Comments**



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME EUREKA MANOR	DATE 10/21/2015
LOCATION 1525 E EUREKA ST, SAN BERNARDINO, CA 92404	INSPECTOR Anies Kondoker

This is a charged inspection.

Observed spa water has good clarity; bottom of the spa is visible from outside the fence.

Observed pool water to be cloudy with some debris accumulation on pool surface. Bottom of the pool is not visible from outside the fence.

No access to the pool enclosure. Office is closed at this time,

One of the following options must be met by Friday, 10/24/15:

- Drain pool water
  - Bring pool water into compliance that meets the code.
- This includes having good water clarity (bottom of the pool shall be easily visible from pool deck).

Non-compliance will result in another charged inspection or further legal action.

Note: a tenant stated that someone worked on the pool this morning.

**Signature(s) of Acknowledgement**

NAME:  
TITLE:

Total # of Images: 0