



REFUSE HAULERS - OFFICIAL INSPECTION REPORT

FACILITY NAME CITY OF ONTARIO SOLID WASTE DEPT				REINSPECTION DATE Next Routine	INSPECTOR Eria Garnica	DATE 6/25/2016
LOCATION 1425 S BON VIEW AV, ONTARIO, CA 91761				PERMIT EXPIRATION 12/31/2016	IDENTIFIER: None	
TIME IN 7:40 AM	TIME OUT 10:20 AM	FACILITY ID FA0008258	RELATED ID PR0005960	PE 2802	SERVICE: 001 - INSPECTION - ROUTINE RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED	

REFUSE HAULERS - Refuse Vehicles

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

28K002 Equipment - Vehicle Specifications

Comply by: 7/27/2016

Not In Compliance

Reference - SBCC - 33.083

Inspector Comments: OBSERVED DECAYING SEAL IN REAR BACK DOOR ON TRUCK NUMBERS:9056, 9058, 9059.
OWNER MUST INSTALL SEAL AND MAINTAIN ON A ROUTINE SCHEDULE FOR TRUCK NUMBERS :9056, 9058, 9059.

OBSERVED CRACKED HOLE ON BACK REAR DOOR ON TRUCK NUMBER 9059.
OWNER MUST REPAIR CRACKED HOLE AND MAINTAIN ON A ROUTINE SCHEDULE.

OBSERVED BROKEN GRILL FRAME ON FRONT OF TRUCK NUMBER 9066.
OWNER MUST REPAIR AND MAINTAIN ON A ROUTINE SCHEDULE.

Description: Collection vehicles and equipment used by permittees for the collection and/or transportation of refuse shall be of a type designed and manufactured specifically for such purposes, as determined by DEHS, and shall comply with the following minimum specifications: (a) All vehicle bodies shall be constructed of metal. All joints and seams shall be welded and leakproof. (b) All refuse compartment doors shall be tight-fitting and shall not leak any contents of the collected refuse. (c) All vehicles classified over three-quarter ton by the manufacturer shall be equipped with an automatic dumping mechanism.

28K020 Identification

Comply by: 7/27/2016

Not In Compliance

Reference - SBCC - 33.0830 (d)

Inspector Comments: OBSERVED BROKEN LICENSE PLATES ON TRUCK NUMBERS: 9058,9059,9056,9070.

OWNER MUST GET NEW LICENSE PLATES ON TRUCK NUMBERS: 9058,9059,9056,9070 AND MAINTAIN ON A ROUTINE SCHEDULE.

OBSERVED MISMATCHED LICENSE PLATES FOR TRUCK NUMBERS: 9087 LICENSE PLATE NUMBERS: 1264458 AND 1237369, 9090 LICENSE PLATE NUMBERS: 1309127 AND 1302335 ,9091 LICENSE PLATE NUMBERS: 1261542 AND 1302356.

OWNER MUST HAVING MATCHING LICENSE PLATES FOR TRUCK NUMBERS 9087, 9090, AND 9091.

Description: The permittee's name or firm name and telephone number shall appear in legible letters not less than three (3) inches high. The business address, if provided, shall appear in letters not less than two (2) inches high on both sides of the vehicle.

Overall Inspection Comments



Public Health
Environmental Health Services

REFUSE HAULERS - OFFICIAL INSPECTION REPORT

FACILITY NAME CITY OF ONTARIO SOLID WASTE DEPT	DATE 6/25/2016
LOCATION 1425 S BON VIEW AV, ONTARIO, CA 91761	INSPECTOR Eria Garnica

Please send pictures of repairs to email address: Eria.Garnica@dph.sbcounty.gov

Inspected refuse trucks- Ontario

License: Truck#:

1302337	9067
1408944	9110
1140354	9041
1140409	9043
1157363	9056
1157364	9058
1140434	9056
1183160	9066
1181467	9069
1181466	9070
1223348	9079
1245817	9080
1257409	9081
1257406	9082
1257407	9083
1257411	9084
1257408	9085
1264458	9087
1264459	9088
1264457	9089
1309127	9090
1261542	9091
1315609	9092
1319978	9093
1319980	9095
1302345	9097
1367365	9098

Deleted trucks:

License: truck #:

1140400	9042
1130520	9038
1130523	9039
1083434	9040
1140356	9044
1140355	9045
1140357	9046
1140358	9047
1140418	9048
1140419	9049
1140431	9051
1157371	9054
1083466	9057

Signature(s) of Acknowledgement



Public Health
Environmental Health Services

www.SBCounty.gov
www.SBCounty.gov/dph/dehs

REFUSE HAULERS - OFFICIAL INSPECTION REPORT

<small>FACILITY NAME</small> CITY OF ONTARIO SOLID WASTE DEPT	<small>DATE</small> 6/25/2016
<small>LOCATION</small> 1425 S BON VIEW AV, ONTARIO, CA 91761	<small>INSPECTOR</small> Eria Garnica

NAME:
TITLE:

Total # of Images: 0