



REFUSE HAULERS - OFFICIAL INSPECTION REPORT

FACILITY NAME AGUA MANSA MRF			REINSPECTION DATE Next Routine	INSPECTOR Eria Garnica	DATE 6/29/2016
LOCATION 1830 AGUA MANSA RD, RIVERSIDE, CA 92509			PERMIT EXPIRATION 12/31/2016	IDENTIFIER: None	
TIME IN 4:15 PM	TIME OUT 5:30 PM	FACILITY ID FA0022902	RELATED ID PR0030155	PE 2802	SERVICE: 001 - INSPECTION - ROUTINE RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED

REFUSE HAULERS - Refuse Vehicles

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

28K002 Equipment - Vehicle Specifications

Compliance Date: Not Specified
Not In Compliance
Reference - SBCC - 33.083

Inspector Comments: Observed holes on drivers side and back on bin number 1143 of the truck number:1227 and license plate numbers: 9D97369, Holes in back bin number 8984, truck number: 1094 and license plate number 9d71495, holes in back of bin number 8986, truck number 8457 and license plate number 9e91115 - far right, top of passenger side.
Owner must repair holes on bin numbers: 1143, 8984, 8986 of the trucks and maintain on a routine schedule.

Description: Collection vehicles and equipment used by permittees for the collection and/or transportation of refuse shall be of a type designed and manufactured specifically for such purposes, as determined by DEHS, and shall comply with the following minimum specifications: (a) All vehicle bodies shall be constructed of metal. All joints and seams shall be welded and leakproof. (b) All refuse compartment doors shall be tight-fitting and shall not leak any contents of the collected refuse. (c) All vehicles classified over three-quarter ton by the manufacturer shall be equipped with an automatic dumping mechanism.

28K020 Identification

Compliance Date: Not Specified
Not In Compliance
Reference - SBCC - 33.0830 (d)

Inspector Comments: Observed broken license plate 9D15796 on truck number 1038.
Owner must receive a new license plate for truck.

Description: The permittee's name or firm name and telephone number shall appear in legible letters not less than three (3) inches high. The business address, if provided, shall appear in letters not less than two (2) inches high on both sides of the vehicle.

Overall Inspection Comments



Public Health
Environmental Health Services

www.SBCounty.gov
www.SBCounty.gov/dph/dehs

REFUSE HAULERS - OFFICIAL INSPECTION REPORT

FACILITY NAME AGUA MANSA MRF	DATE 6/29/2016
LOCATION 1830 AGUA MANSA RD, RIVERSIDE, CA 92509	INSPECTOR Eria Garnica

Please send pictures of repairs to email address: Eria.Garnica@dph.sbcounty.gov

Inspected trucks- 1830 Agua Mansa Rd.,Riverside

License:	Truck #:
9D15796	1038
9D97369	1227
9B58163	1228
9B47715	1229
9E47604	1457
9E47603	1458
9B92458	8424
9A98432	8428
9B82411	8792
9D61592	1092
9D71495	1094
9D61591	1095
9E34799	1146
9D64923	1147
9D40084	8212
9D08026	8309
9D20972	8377
9D08046	8425
9D08058	8457
9D08060	8458
9D40070	8644
9B58332	8693
9B58330	8694

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0